

1 Products affected

Product hierarchy no. *				Part no.	SBU	Type / Description	Customer part no.
SBU	PG	PUG	Type				
02	007	050	0000002081	0888.0001	Cord retaining clamp		



*SBU (2-digit) / PG (3-digit) / PUG (3-digit) / Type (10-digit)

2 Type of change

Change of Country of origin on packaging label

3 Detailed description of change

Country code for country of origin changed from GB to TN.

Old label	New label
 <p>The old label features the Schurter logo, P/N 0888.0001, a QR code, and a RoHS COMPLIANT logo. It includes a barcode for quantity (50), a lot barcode (123456789), and a date barcode (1850). The product name 'BUEGEL KOMPLETT' and description 'cord retaining clamp' are present. At the bottom, the country of origin is listed as 'SE CoO GB'.</p>	 <p>The new label is identical to the old one but with the country of origin changed to 'SE CoO TN'. The 'TN' is circled in red in the image.</p>

4 Reason of change

Data error in system.

5 Release date

The change takes effect in ww 50/2018 (Date code 1850 or higher on label).

6 Impact of change and recommended action

Form	No	-
Fit	No	-
Function	No	-
Manufacturing	No	-
Label	Yes	Change on label
Packaging	No	-

7 Reference Documents / Attachments

Kind of document	Remarks
Datasheet Cord retaining kit	

Product Change Notification					PCN Cord retaining kit		
owner	creation date	release date	released by	change order no	rev	page	D10-032-730
huberth	13.12.2018	25.07.2019	limachcl	2016835	A	1 of 1	